



The SandenVendo Company
10710 Sanden Drive, Dallas, TX 75238

**TECHNICAL SERVICES
ADVISORY MEMO 00-0509**

To: **Distribution**

From: **Technical Services**

Date: **May 8, 2009**

Subject: Condensation forming on the outside of the door

Remarks: For Your Review

Sanden Vendo has created a kit to substantially reduce condensation from forming on the outside of the door hinge on the SXY 30 , 40 machines. Kit **P/N 1173375** for the SXY 40 and **P/N 1173387** for the SXY 30 HINGE CONDENSATION REDUCTION.

If you need further information or assistance, please call Sanden Vendo Technical Service at
800-344-7216 ext 9935

The information contained in this message is privileged and confidential information intended only for the use of the individual or entity to whom addressed. If the reader of this message is not the intended recipient, such recipient is advised that any dissemination, distribution or copy of this information is strictly prohibited.