



The SandenVendo Company
10710 Sanden Drive, Dallas, TX 75238

**TECHNICAL SERVICES
ADVISORY MEMO 00-**

To: Distribution

From: Technical Services

Date: May 11, 2009

Subject: Fill the gap at the top of the bucket

Remarks: For Your Review

Sanden Vendo has created a kit to fill in the gap at the top of the bucket on the Vue and SXY model machines to prevent fingers getting pinched in the bucket. Kit **P/N 1173182** Bucket gap filler kit.

If you need further information or assistance, please call Sanden Vendo Technical Service at
800-344-7216 ext 9935

The information contained in this message is privileged and confidential information intended only for the use of the individual or entity to whom addressed. If the reader of this message is not the intended recipient, such recipient is advised that any dissemination, distribution or copy of this information is strictly prohibited.